

HABS
ID.
11-EAPo.
1-A-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

United States Border Inspection Station , Customs Officers Residence HABS No. ID-101-A
West Side of U.S. Route 95
Eastport
Boundary County
Idaho

Harvey S. Rice, Photographer June 1988

United States Border Inspection Station, Customs Officers Residence

EXTERIOR PHOTOGRAPHS

- ID-101-A-1 SOUTH AND EAST ELEVATIONS, VIEW TO NORTHWEST
- ID-101-A-2 NORTH AND WEST ELEVATIONS, VIEW TO SOUTHEAST
- ID-101-A-3 SOUTH AND WEST ELEVATIONS, VIEW TO NORTH

INTERIOR PHOTOGRAPHS

- ID-101-A-4 ARCHWAY AND CHINA CABINETS IN DINING ROOM, VIEW TO NORTH INTO LIVING ROOM
- ID-101-A-5 FIREPLACE IN LIVING ROOM, VIEW TO SOUTH

ORIGINAL DRAWINGS (FROM THE GENERAL SERVICES ADMINISTRATION, AUBURN, WASHINGTON)

- ID-101-A-6 Photocopy of an original drawing
3 May 1935
ELEVATIONS AND FLOOR PLANS
- ID-101-A-7 Photocopy of an original drawing
24 May 1963
MISCELLANEOUS REPAIRS & IMPROVEMENTS